NTSB ID: DEN02LA088 Aircraft Registration Number: N238SP

Occurrence Date: 08/04/2002 Most Critical Injury: None

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place	State CO	Zip Code 80112	Local Time	Time Zone MDT	
Englewood		00112	1140	ו טועו	
Airport Proximity: On Airport	Distance From	m Landing Facility:		Direction Fro	m Airport:

Aircraft Information Summary

7 di Ciait inionnation Gammary		
Aircraft Manufacturer	Model/Series	Type of Aircraft
Cessna	172S	Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On August 4, 2002, approximately 1140 mountain daylight time, a Cessna 172S, N238SP, registered to EDB Air, Inc., and operated by Key Lime Flight School, both of Englewood, Colorado, was substantially damaged when it impacted terrain during a touch-and-go landing at Centennial Airport, Englewood, CO. The instructor pilot and commercial pilot receiving instruction were not injured. Visual meteorological conditions prevailed, and no flight plan had been filed for the instructional flight being conducted under Title 14 CFR Part 91. The local flight originated approximately 1030.

According to the pilot receiving instruction, he was flying the airplane from the right seat. He made four touch-and-go landings. The fifth approach was normal, with a flap setting of 30 degrees, but the flare was too high and the airplane landed hard and bounced. He added full power and began to fly down the runway for a go-around. He said the instructor "adjusted the flap position and the airplane lost all lift and fell to the runway." The airplane slid across a grassy area and came to a halt on the taxiway. The nose landing gear was collapsed and the firewall was buckled. Both propeller blades were curled forward.

The following weather observation was recorded shortly after the accident: wind, variable at 4 knots; visibility, 10 statute miles; temperature, 81 degrees Fahrenheit; dew point, 52 degrees Fahrenheit; altimeter, 30.25. The airport elevation was 5,883 ft. msl, and the calculated density altitude was 8,385 ft. msl.

NTSB ID: DEN02LA088

Occurrence Date: 08/04/2002

AVIATION Occurre					rence Type: Accident								
Landing Facility/Approach Info	rmation												
Airport Name			Airport	ID:	Airport Eleva	tion	Run	Runway Used		Runway Length		Run	way Width
CENTENNIAL			APA		5883 Ft.	5883 Ft. MSL 17R 1000)2		100	i		
Runway Surface Type: Asphalt													
Runway Surface Condition: Dry													
Type Instrument Approach: NONE													
VFR Approach/Landing: Touch and Go													
Aircraft Information													
Aircraft Manufacturer Cessna			"	Model/ 172S	Series					Serial 172S		er	
Airworthiness Certificate(s): Normal													
Landing Gear Type: Tricycle													
Homebuilt Aircraft? No	Number of Seats: 4				Certified Max Gross Wt.			2550 LBS N			Number of Engine		»: 1
=				Engine Manufacturer: Model/Series: Lycoming IO-360						Rated Power: 180 HP			
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection			Time Since Last Inspection					Airframe Total Time		
100 Hour			06/20	06/2002 66.4 Ho				ours 602.9 Hours			02.9 Hours		
- Emergency Locator Transmitter (EL	.T) Information									•			
ELT Installed? Yes	ELT Opera	ted? No	ELT Aided in Locating Accident Site? No)			
Owner/Operator Information													
Registered Aircraft Owner			Street Address 7625 S. Peoria St										
EDB Air Inc.			7625 S. Peoria St. City							Stat	te	Zip Code	
										CO		80112	
Operator of Aircraft			Street Address 7355 S. Peoria St.										
Key Lime Flights			City Englewood							Star CO	te	Zip Code 80112	
Operator Does Business As:			-				Op	perator Desig	gnator Co	ode:			
- Type of U.S. Certificate(s) Held: No	ne												
Air Carrier Operating Certificate(s):													
Operating Certificate:			Operator Certificate:										
Regulation Flight Conducted Under:	Part 91: Gener	al Avia	tion										
Type of Flight Operation Conducted:	Instructional												
		FACT	IIAI R	EPO	RT - AVIATI	ON							Page 2

NTSB ID: DEN02LA088

Occurrence Date: 08/04/2002

AVIATION Occurrence Type: Accident					cident							
First Pilot Information												
Name					City			St	tate	Date of Birth	Age	
On File					On File	le On File On File					36	
Sex: M Seat Occupied	: Left	Prir	ncipal Profes	sion: Police				Certific	ate Num	ber: On File		
Certificate(s): Flight	nt Instructor;	Commercia	al									
Airplane Rating(s): Multi-engine Land; Single-engine Land												
Rotorcraft/Glider/LTA: None												
Instrument Rating(s): Airplane												
Instructor Rating(s): Airplane Single-engine; Instrument Airplane												
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review? 08/2001												
Medical Cert.: Class 1	ivers/lim.		Date	of Last N	Medical E	Exam: 04/2002						
•												
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	I Actual	nstrument Sin	nulated	Rotorcraft	Glider	Lighter Than Air	
Total Time	466	347	447	19	51		5	74				
Pilot In Command(PIC)	388	310	410	12	45		5	74				
Instructor	67	67	67		10	+	_	30				
Last 90 Days	41 15	30 15	30 15		3			2				
Last 30 Days Last 24 Hours	15	15	15		3		+					
Seatbelt Used? Yes	Shou	lder Harness	Used? Yes		Toxio	cology Per	ormed?	No	s	Second Pilot? Ye	es	
					l							
Flight Plan/Itinerary												
Type of Flight Plan Filed: No	one											
Departure Point					Stat	State Airport Identifier		entifier	Departure Time		Time Zone	
Same as Accident/Incide	ent Location					APA		1030)	MDT	
Destination					Stat	e A	Airport Identifier					
Local Flight												
Type of Clearance: None												
Type of Airspace: Class	D											
Weather Information												
Source of Briefing: Unkno	wn											
Method of Briefing: Unkno	own											
			FACTUAL	REPORT -	AVIATIO	N					Page 3	

NTSB ID: DEN02LA088

Occurrence Date: 08/04/2002

Occurrence Type: Accident

	FIYBOR		Occurrent	,е туре.	Acciden	ι								
Weather	Weather Information													
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Di	stance Froi	m Accid	Direction From	n Accident Site	÷				
KAPA	1153	MDT	5883 Ft.	. MSL					Deg. Mag.					
Sky/Lowes	st Cloud Condition: Few					75 Ft. A0	GL	Condition of Light: Day						
Lowest Ce	eiling: None		Ft.	AGL	Visibi	lity:	10	SM	Alti	meter:	30.25	"Hg		
Temperatu	ure: 27 °C [11 °C	Wind	Direction:				Dei	nsity Altitude:	8385	Ft.			
Wind Spee	ed: 4	Gusts:		Weath	ner Condti	ons at Acci	ident S	Site: Visual C	Cond	itions				
Visibility (F	RVR): Ft.	Visibility (RV	/V)	SM	Intensity	of Precipit	tation:							
Restrictions to Visibility: None														
Type of Precipitation: None														
Accident	Information													
Aircraft Da	mage: Substantial		Aircraft Fir	Aircraft Fire: None					losio	n None				
Classificati	ion: U.S. Registered/U.	.S. Soil												
- Injury Su	mmary Matrix	Fatal Seri	rious Mino)r	None	TOTAL								
First Pi	ilot	<u></u>			1	1								
Second	d Pilot						7							
Studen	nt Pilot						1							
Flight I	Instructor				1	1	1							
Check	Pilot						1							
Flight E	Engineer						1							
Cabin /	Attendants						1							
Other 0	Crew						1							
Passer	ngers			\neg			1							
- TOTAL /	ABOARD -			\neg	2	2	2							
Other C	Ground						1							
- GRANE	O TOTAL -				2	2	<u>-</u>							

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: DEN02LA088

Occurrence Date: 08/04/2002

Occurrence Type: Accident

							-			
Δ	dт	ını	ıctı	rativ	10	Int	^rı	മാ	tιΛ	n
$\overline{}$	um		IJΙ	au	v C		OH	III C	เเบ	

Investigator-In-Charge (IIC)

Arnold W. Scott

Additional Persons Participating in This Accident/Incident Investigation:

Larry Rockhold FAA FSDO 26805 E. 68th Ave, #200 Denver, CO 80249